

Static and Dynamic Strength of Scarf-Repaired Thick-Section Composite Plates

by Bazle A. Gama, Stephane Mahdi, Curt Cichanowski, Shridhar Yarlagadda, and John W. Gillespie, Jr.

ARL-CR-549 September 2004

prepared by

Center for Composite Materials University of Delaware Newark, DE 19716

under contract

DAAD19-01-2-0005

NOTICES

Disclaimers

The findings in this report are not to be construed as an official Department of the Army position unless so designated by other authorized documents.

Citation of manufacturer's or trade names does not constitute an official endorsement or approval of the use thereof.

Destroy this report when it is no longer needed. Do not return it to the originator.

Army Research Laboratory

Aberdeen Proving Ground, MD 21005-5069

ARL-CR-549 September 2004

Static and Dynamic Strength of Scarf-Repaired Thick-Section Composite Plates

Bazle A. Gama, Stephane Mahdi, Curt Cichanowski, Shridhar Yarlagadda, and John W. Gillespie, Jr. Center for Composite Materials University of Delaware, Newark, DE

prepared by

Center for Composite Materials University of Delaware Newark, DE 19716

under contract

DAAD19-01-2-0005

Approved for public release; distribution is unlimited.

REPORT DOCUMENTATION PAGE

Form Approved OMB No. 0704-0188

Public reporting burden for this collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing the burden, to Department of Defense, Washington Headquarters Services, Directorate for Information Operations and Reports (0704-0188), 1215 Jefferson Davis Highway, Suite 1204, Arlington, VA 22202-4302. Respondents should be aware that notwithstanding any other provision of law, no person shall be subject to any penalty for failing to comply with a collection of information if it does not display a currently valid OMB control number.

PLEASE DO NOT RETURN YOUR FORM TO THE ABOVE ADDRESS.

1. REPORT DATE (DD-MM-YYYY)	2. REPORT TYPE	3. DATES COVERED (From - To)	
September 2004	Final	November 2002–March 2003	
4. TITLE AND SUBTITLE	<u> </u>	5a. CONTRACT NUMBER	
Static and Dynamic Strength of	Scarf-Repaired Thick-Section Composite Plates	DAAD19-01-2-0005 (CMT)	
The state of the s		5b. GRANT NUMBER	
		5c. PROGRAM ELEMENT NUMBER	
6. AUTHOR(S)		5d. PROJECT NUMBER	
Bazle A. Gama, Stephane Mah	di, Curt Cichanowski, Shridhar Yarlagadda, and	622618.AH80	
John W. Gillespie, Jr.	5e. TASK NUMBER		
		5f. WORK UNIT NUMBER	
7. PERFORMING ORGANIZATION NAT Center for Composite Materials University of Delaware Newark, DE 17916	8. PERFORMING ORGANIZATION REPORT NUMBER		
9. SPONSORING/MONITORING AGEN	CY NAME(S) AND ADDRESS(ES)	10. SPONSOR/MONITOR'S ACRONYM(S)	
U.S. Army Research Laborator	ARL-CR-549		
ATTN: AMSRD-ARL-WM-M Aberdeen Proving Ground, MD	11. SPONSOR/MONITOR'S REPORT NUMBER(S)		
	21005-5069		

12. DISTRIBUTION/AVAILABILITY STATEMENT

Approved for public release; distribution is unlimited.

13. SUPPLEMENTARY NOTES

14. ABSTRACT

Composite structural armor is typically a sandwich construction consisting of thick-section composite, rubber, and ceramic layers, which are combined to provide an optimal balance of structural and ballistic performance at minimum weight. Our focus was on the scarf repair of the thick-section plain weave S-2 Glass/SC15 composite subjected to static and dynamic loading. Deliberate damage to backing plates was repaired at elevated temperatures using induction heating and at room temperature. The static response of control and repaired plates was compared via four-point bend testing. The effect of three scarf angles and four repair adhesives was quantified. Using these repair techniques, renewal of stiffness was achievable, except for the case of the highly ductile, low-stiffness adhesive. The renewal of moment capacity of the repair beams was highly dependent on the scarf angle for various adhesives, and a maximum renewal of strength was 60%. The dynamic strength of scarf patch-repaired composite specimens was investigated through axial compression strength testing using a split-Hopkinson bar. Under dynamic loading, the axial strength was found to be dependent on the scarf angle and rate of loading. Loci of failure are reported for the various materials, scarf angles, and loading conditions.

15. SUBJECT TERMS

repair, induction cure, thick-section composites, axial compression, Hopkinson bar, failure analysis, punch shear test, energy absorption, S-2 Glass/SC15, hybrid

16. SECURITY CLASSIFICATION OF:		17. LIMITATION OF ABSTRACT	18. NUMBER OF PAGES	19a. NAME OF RESPONSIBLE PERSON Bazle A. Gama	
a. REPORT	b. ABSTRACT	c. THIS PAGE		20	19b. TELEPHONE NUMBER (Include area code)
UNCLASSIFIED	UNCLASSIFIED	UNCLASSIFIED	UL	38	302-831-8352

Standard Form 298 (Rev. 8/98) Prescribed by ANSI Std. Z39.18

Contents

Lis	et of Figures	iv
Lis	et of Tables	iv
Ac	knowledgments	v
1.	Introduction	1
2.	Test Methods	3
3.	Materials and Repair Procedure	4
	3.1 Materials	4
	3.2 Repair Procedure	5
4.	Induction Repair	5
5.	Static Performance of Scarf-Repaired Composite Beams	7
6.	Dynamic Axial Compression of Scarf-Repaired Composite Plates	9
7.	Conclusions	12
8.	References	14
Dis	stribution List	16

List of Figures

Figure 1. Cross section of a model four-layer structural armor (5)1
Figure 2. Ballistic damage of a composite structural armor: (a) the ceramic tiles after the cover layer have been removed and (b) cross section (8)
Figure 3. Four-point bending testing of scarf-repaired composite backing plate3
Figure 4. Hopkinson bar procedure for dynamic axial compression of scarf repair composite specimens
Figure 5. Induction-heating of the elevated-temperature cure adhesives6
Figure 6. The renewal in static strength of the repaired backing plates8
Figure 7. Hopkinson bar responses of Hysol EA9359.3 induction-cured scarf-repaired composite specimens under axial compression
Figure 8. Stress equilibrium in Hysol EA9359.3 scarf-repaired composite specimens10
Figure 9. Stress analysis of scarf-repaired composite specimens under dynamic axial compressive load
Figure 10. Axial compressive strength of scarf-repaired composite specimens under dynamic compressive load
Figure 11. Fracture surfaces of scarf-repaired composite specimens under dynamic axial compression.
Figure 12. Stresses at failure in the rotated coordinate system of the scarf-repaired composite specimens
List of Tables
Table 1. Bending stiffness (per unit width) of the repaired backing plates7
Table 2. Bending moment at failure of the repaired baking plates8

Acknowledgments

The authors wish to acknowledge the financial support provided by the Strategic Environmental Research and Development Program (grant no. DAAL01-98-K-0058) and the Composite Materials Technology Collaborative Program sponsored by the U.S. Army Research Laboratory under Cooperative Agreement DAAD19-01-2-0005.

INTENTIONALLY LEFT BLANK.

1. Introduction

Composite structural armor typically consists of different material layers stacked together to provide unique structural and ballistic properties, as well as satisfying other multifunctional requirements (e.g., fire, smoke, and toxicity [FST] resistance, electromagnetic shielding, etc.) (1–4). This program used a simplified four-layer configuration that consists of a composite cover layer for durability, a layer of ceramic tile for ballistic protection, a rubber layer, and a thick composite backing plate for structural and ballistic performance (figure 1). Fabrication of the composites used the vacuum assisted resin transfer molding (VARTM) process, which has been shown to provide superior mechanical properties in a single-step operation as compared to bonding individual layers in a multistep process (5). Additional details on structural behavior can be found in (5–7).




Figure 1. Cross section of a model four-layer structural armor (5).

Under ballistic impact, both the cover layer and the backing plates could be completely perforated, and the extent of damage in the ceramic tiles varied from a single tile to all of the tiles surrounding the impact site (see figure 2). Multiple interfaces in the backing plate also had delaminations that were larger than the extent of damage to the ceramic tiles (i.e., three tiles in length). Extensive fiber damage also occurred at the impact site. Experiments have shown that such damage degrades the ballistic performance of the structural armor (8). The compression strength after ballistic impact was also shown to drop to levels approaching 25% of the virgin strength (9). Repair that is capable of renewing the structural and ballistic performance after a ballistic impact is a key issue for the use of composites for Future Combat Systems (FCS).

The extent of damage in different layers determines the level of repair to be performed. Different repair strategies and repair methods that use conventional repair techniques or induction curing techniques have been documented in previous studies (8, 10). Three levels of repair have been identified according to the level of damage through the thickness of the armor. Level I is concerned with the repair of the cover layer only, as in the case of damage due to a low-velocity impact. Level II represents the case of the repair of both the cover layer and the ceramic strike face. Finally, Level III addresses the repair of all the layers that compose the

structure, including the repair of the composite backing plate, as in the case of the high-velocity ballistic impact damage shown in figure 2. A repair by resin infusion was attempted (8), but it was shown to provide only moderate improvement in the ballistic performance of the repaired panels. Because resin infusion does not effectively repair fiber damage, the present study evaluates a scarf repair that enables all damaged materials to be replaced for Level III repairs.




Figure 2. Ballistic damage of a composite structural armor: (a) the ceramic tiles after the cover layer have been removed and (b) cross section (8).

The repair should renew stiffness, strength, and ballistic performance to meet design requirements. The present effort on scarf repair builds on the procedures developed by Gama et al. (10) who demonstrated a Level III repair of structural armor. The repair involved the removal and replacement of all the layers shown in figure 1, including that of the composite backing plate. Following the removal of the damaged cover layer and the damaged ceramic tiles, the damaged region of the backing plate was removed using a wet grinding tool to form a circular hole. The edge of the hole was machined to produce a 45° scarf angle. The backing plate was then repaired with an adhesive-bonded flush scarf plug of the same material, and the ceramic and cover layer were replaced. The repair to the thin cover layer used a flush plug repair (i.e., butt joint). The repair of the entire cross-section was done in a single-step operation from one-side that used a vacuum bag for consolidation and induction heating for rapid heating and cure. Various susceptors were used at the various interfaces to locally heat the adhesive bond lines to cure temperatures without overheating any single interface. A repaired demonstrator panel was manufactured to prove process viability, but was not tested. These repair techniques were used in the present study to fabricate test specimens to characterize the structural performance of the backing plate with scarf repair subjected to static and dynamic loading.

Composite structural armor is subjected to bending moments and shear forces due to terrain-induced loads and lateral impacts. Some understanding of the complex interaction between layers of structural armor is needed to establish simple test methods that evaluate Level III repair approaches and maintain some relevance to the application loads. In previous work (11), the finite element method was used to model the deformation behavior of the armor in bending. The through-thickness strain distribution deviates greatly from that of the linear classical analysis due to the compliant rubber layer that decouples the ceramic from the composite backing plate. These results show that it is possible to idealize the behavior of the backing plate in the structural

armor as a beam subjected to bending loads. In addition, in-plane axial compression loads can also be used to evaluate the strength of bonded joints. The present study focused on developing simple test methods to quantify the performance of scarf-repaired thick-section composite backing plates of composite structural armor.

2. Test Methods

The four-point bending test was selected to characterize the static behavior of the virgin and repaired beams. The nominal dimension of the test beam was $889 \times 30 \times 13.2$ mm. The support span was 762 mm, which provided a span-to-thickness ratio of 57.7. The span of the loading noses was sufficiently large (381 mm) to include the scarf repair. The specimen and test configurations are shown in figure 3. An Instron 8562 (servo-hydraulic) machine equipped with a custom built four-point bend test fixture (support and loading nose diameter of 25.4 mm) was used to conduct the experiment at a constant crosshead displacement rate of 2.5 mm/min. Load and crosshead displacement data were collected using the Instron Series IX data acquisition software.




Figure 3. Four-point bending testing of scarf-repaired composite backing plate.

Dynamic axial compression tests of scarf-repaired composite joints were performed using the compression split Hopkinson pressure bar (SHPB) technique (12) (figure 4). The results generated were representative of the response of the scarf repair joints loaded in axial compression. The striker bar, the incident bar, and the transmitter bar were all made from Inconel 718 alloy (Young's modulus–200 GPa, bar velocity–4920 m/s, Poisson's ratio–0.29, and diameter–19.05 mm). Specimens of a nominal cross section (13.5 × 13.5 mm) were machined from scarf-repaired composite plates. The lengths of the specimens were 37.5, 70, and 90 mm for 45, 18.4, and 11.3° scarf angles, respectively. In order to load such long specimens for sufficient duration, a long striker bar (711 mm) was used to produce a long incident pulse. A rubber disk was used between the striker bar and the incident bar to shape the pulse and to uniformly load the specimen. The impact velocity of the striker bar was varied between 5 and 10 m/s, which produced a displacement rate of 2.5–5 m/s. Maximum force at failure was calculated using a "3-wave" analysis from the incident, reflected, and transmitted stress pulses as obtained from each test. A minimum of two specimens was tested for each scarf ratio and adhesive used.




Figure 4. Hopkinson bar procedure for dynamic axial compression of scarf repair composite specimens.

3. Materials and Repair Procedure

3.1 Materials

The backing plate considered in the present work consisted of 22 layers of Knytex plain weave S-2 Glass* fabric of areal density 0.81 kg/m². The lay-up orientation used was (0°/90°) (i.e., the fabric warp direction is at 0°, and the weft direction is at 90°). The backing plates were fabricated by VARTM (5), using an Applied Poleramic SC15 epoxy resin system, specifically developed for the VARTM process. SC15 has a tensile modulus of 2.7 GPa and strain to failure of 6%. The SC15 system gels at room temperature (8–12 hr). Additionally, a 4-hr post-cure at 149 °C was used. The total thickness of the backing plate was nominally 13.2 mm with a volume fraction of ~50% and <1% void content.

The choice of a proper adhesive system for repair of structures is always crucial. The selected adhesive must offer good mechanical properties, high toughness, and meet service temperature requirements. It has to be polyvalent and adhere well to different materials. Also, a moderate viscosity is needed to fill the gaps in between the ceramic tiles and the adhesive should be easily spread. Finally, cure at a relatively low temperature in a short period of time is desirable.

Four adhesives were chosen for this study that offered a broad range of properties. The Dexter Hysol[†] EA9359.3NA adhesive is a two-part system that cures at 82 °C for 1 hr. According to the manufacturer's datasheet (*13*), it has a bulk tensile modulus of 2.2 GPa, a tensile strength of 31 MPa, and an elongation at failure of 10%. The Dexter Hysol EA9394 adhesive is also a two-part system that cures at 66 °C for 1 hr. According to the manufacturer's datasheet (*13*), it has a bulk tensile modulus of 4 GPa, a tensile strength of 46 MPa, and a much lower elongation at failure of 1.7%. Both systems have been successfully cured using induction heating of structural armor. The use of a room-temperature cure adhesive was also considered. Plexus[‡]

^{*} S-2 Glass is a registered trademark of Owens Corning.

[†] Hysol is a registered trademark of the Dexter Corporation.

[‡] Plexus is a registered trademark of ITW Plexus, a business unit of Illinois Tool Works.

MA425 is a two-part methacrylate adhesive that cures in 30 min at room temperature. This adhesive provides good gap filling capability as well as a much higher elongation to failure (120%). This adhesive has a lower tensile modulus (345 MPa) and strength (17 MPa) compared to the elevated temperature cure adhesives. The fourth adhesive was also a methacrylate (Plexus AO420), which has similar mechanical properties, but a much lower curing time of 6 min.

3.2 Repair Procedure

The scarf patch repair concept shown in figure 3 is a very efficient way of repairing highly loaded composite structures. Care must normally be taken to ensure that the scarf angle is low enough to allow for a smooth stress transfer between the two adherends. Scarf repairs of thin aerospace structures are commonly limited to angles ranging between 2 and 6°. This is not practical in thick-section laminates. In the present work on the repair of thick sections, the scarf patch was limited to a diameter of 350 mm (~3 tile diameters, where extensive fiber damage occurs). Therefore, the maximum allowable scarf angle was ~11° (i.e., 1/5 scarf ratio for a 13.2-mm-thick adherend). Three scarf angles were investigated using our test methods. The angles included 45 (1/1 scarf ratio), 18.4 (1/3 scarf ratio), and 11.3° (1/5 scarf ratio).

Twenty backing plates, 889 mm long and 30 mm large, were fabricated by the VARTM process (5) and used for the characterization of the static and ballistic performance of the repairs. Two backing plates were kept virgin and tested as control beams. Eighteen beams were machined to receive the scarf patch repairs, two beams for each repair adhesive and scarf angle combination. For the repair, a distance equal to 101.6 mm separates the lower tips of the scarf, as shown in figure 3b. The placement of the repair patch only required that the surfaces in contact be completely wetted with the repair adhesive. The repair stack was then placed in a vacuum bag for hardening of the repair adhesive.

The backing plates repaired using the elevated-temperature cure Hysol adhesives were cured by induction-heating technique as described in the next section. The Plexus repaired beams were cured at room temperature. The quality of the control and repaired beams was visually observed to be very good.

4. Induction Repair

Induction heating is a noncontact method by which electrically conductive materials (susceptors) are heated in an electromagnetic field. This technique has successfully heated multiple interfaces as shown in figure 1 in a single-step operation, with the use of appropriately placed susceptors (14). A stainless steel mesh susceptor, with a wire density of $5 \times 5/\text{cm}^2$ and a wire diameter of 0.165 mm, was used in the present study. The stainless steel mesh was cut to the shape of the area to be bonded, cleaned with acetone, impregnated with adhesive, and then placed in the bond area between the parent and patch laminate (which was also covered with

adhesive). The stack was then vacuum bagged and placed horizontally under the induction coil at an optimal stand-off distance. The power setting of the induction generator, the coil shape (see figure 5), and the coil stand-off distance were selected for uniform heating of the bond line to the adhesive cure temperature. This relationship was established experimentally by using an actual repair backing plate that incorporated the susceptor mesh wrapped in a Kapton* film to allow multiple heating cycles. A two-turn rectangular coil was used for the fabrication of the 45 and 18.4° scarf repair as shown in figure 5a. A four-turn spiral coil (shown in figure 5b) was used for the fabrication of the 11.3° scarf repairs. The 11.3° scarf repairs were bonded in two passes, in order to ensure a complete coverage of the bond area with the induction-heating field. The stack was placed underneath the induction coil at a selected distance, and the power was increased from 50% to 100%, in 10% increments. Process temperatures were recorded with a thermal camera and an embedded thermocouple.




Figure 5. Induction-heating of the elevated-temperature cure adhesives.

An AGEMA Thermo-vision[†] 900 thermal camera was positioned in front of the setup to capture the full-field surface temperature of the bond area in real time. An E-type thermocouple was placed at the susceptor/adherend interface to monitor the internal bond-line temperature. The bondline temperature was slightly higher than the surface temperature due to heat losses. Steady-state was reached in a few minutes for each increment in power. Once a susceptor steady-state temperature of ~82 (i.e., the cure temperature of Hysol EA9359.3) and 66 °C (i.e., the cure temperature of Hysol EA 9394) was achievable within the range of the power

^{*} Kapton is a registered trademark of DuPont.

[†] Thermo-vision is a registered trademark of AGEMA Company.

settings, the stand-off distance was recorded, and this combination was used for further bonding trials. The steady-state surface temperatures, recorded from the thermal camera, are presented in figure 5 for the 18.4° scarf and the 11.3° scarf repairs.

5. Static Performance of Scarf-Repaired Composite Beams

The load-deflection behavior of all the specimens tested was observed to be linear elastic until failure. Because the span-to-thickness ratio of the beams was large (i.e., 57.7), classic beam theory was used to experimentally determine the bending stiffness per unit width of the beams under four-point bending.

$$E_f I/b = (P/D_1) \cdot (L^3/96)/b$$
, (1)

where E_f is the flexural modulus, I is the moment of inertia of the cross section, P and D_1 is the instantaneous load and cross-head displacement in the linear-elastic region, L is the length of the support span, and b is the width of the beam. A comparison of the bending stiffness of the control beams with that of the repaired beams is presented in table 1. Results showed a 100% renewal of structural stiffness was attainable with the elevated-temperature cure repair adhesives. However, the room-temperature cure repaired backing plates were more compliant by ~15% due to the lower modulus of the Plexus adhesive (i.e., 0.345 vs. 2.2 GPa for EA9359.3NA). Because stiffness is typically the critical design parameter for composite armor structures, the lower stiffness of the Plexus repaired beams may prevent the use of the Plexus adhesive for repair of composite armor. However, it should be pointed out that the stiffness loss in a 3-D scarf repair is likely to be less than that measured in the 2-D beam specimen.

Table 1. Bending stiffness (per unit width) of the repaired backing plates.

Repair Type	Bending Stiffness (kN-m)
Undamaged	5.75
Elevated-temperature cure repaired	5.75
Room-temperature cure repaired	5.00

The strength renewal of repaired beams was evaluated using the ratio of moment capacity of a repaired beam to that of the control beam. The two baseline specimens (i.e., no repair) failed at an average bending moment of 8.79 kN-m/m (per unit width). The failure mode was observed to be a compressive failure of the fibers on the specimen surface layer. This failure mode did not cause catastrophic failure of the beam, and only a minor change in compliance resulted. However, the moment capacity at the onset of damage was used as the baseline for quantifying the effectiveness of the repairs. The bending moment at failure of all the repaired backing plates tested is summarized in table 2. The values given are an average value from two beams tested with minimal variation. In general, a major reduction in the moment capacity was observed and

Table 2. Bending moment at failure of the repaired baking plates.

Bending moment at failure / unit width (kN-m/m) ^a				
	Hysol EA9359.3NA	Hysol EA9394	Plexus MA425	Plexus AO420
45° scarf (1/1)	1.97	1.65	1.13	0.95
18.4° scarf (1/3)	4.60	3.34	3.36	4.05
11.3° scarf (1/5)	5.49	3.83	5.91	5.44

^a To be compared with that of control beams, i.e., 8.79 kN-m/m.

was strongly dependent on scarf angle and adhesive type. Furthermore, the repaired beams failed suddenly at the adhesive bond line (in contrast to the progressive failure of the baseline). The extent of strength renewal (i.e., renewal of bending moment capacity), with respect to scarf angles and repair adhesives, is shown in figure 6a and 6b and ranges from 10% to 60%. The strength renewal of the induction-cured Hysol adhesives is shown in figure 6a. The repair efficiency of the 45° scarf angle was low (~20%) and was almost independent of the adhesive system used. The structural performance of the 18.4 and 11.3° scarf angles improved significantly as the scarf angle was reduced. It is observed in figure 6a that the Hysol EA9359.3 repaired beams restored as much as 62% of the control strength of the backing plates, compared with only 43% for the beams repaired with the EA9394 adhesive. The improved performance of the Hysol EA9359.3 may be attributed to the higher elongation and toughness of this adhesive system. In a recent study (15), induction-cured EA9359.3 single-lap shear joints tested in tension and four-point bending were also shown to be stronger and tougher than similar EA9394 joints.




Figure 6. The renewal in static strength of the repaired backing plates.

The loci of failure of the repaired backing plates were, nevertheless, found to be similar for both elevated-temperature cure repair systems. The 45° scarf-repaired beams were seen to fail by an interfacial failure at the adhesive/metal mesh interface. Decreasing the scarf angle to 18.4°

resulted in a slight change in the failure mode, and the locus of failure was observed to be interfacial, but 50% between the metal mesh susceptor and the adhesive (top end of the scarf), and 50% between the adhesive and the parent (lower end of the scarf). The 11.3° scarf-repaired beams failed by an adhesive/parent interfacial failure. Some adherend failure was also observed to have occurred.

The structural performance was mainly dependent on the scarf angle because the adhesive properties were similar. The repair efficiency was slightly lower (~10%) for the 45° scarf angle compared to the Hysol adhesives. However, the repair efficiency increased to 40% and 65% for the 18.4 and 11.3° scarf-repaired backing plates, respectively. This level was comparable to that of the induction-cured EA9359.3NA repaired backing plates. The locus of failure of the 45° scarf was in the adhesive. Decreasing the scarf angle to 18.4° promoted a mixed, adhesive/interfacial failure. The 11.3° scarf-repaired backing plates failed by interfacial failure. In summary, the 11.3° scarf angle enabled renewal of moment capacity approaching 65% of the static baseline. This range of scarf angles is considered practical for the repair of thick-section backing plates used in structural armor.

6. Dynamic Axial Compression of Scarf-Repaired Composite Plates

Dynamic axial compression of scarf-repaired composite specimens was performed using the Hopkinson bar technique. The Hopkinson bar responses for Hysol EA9359.3 adhesive repaired specimens are presented in figure 7. All of these specimens failed under dynamic loading. At lower impact velocity, a rubber pulse shaper generates an incident pulse that is almost triangular in shape. The incident pulse becomes trapezoidal in shape at higher impact velocities. The 11.3° scarf specimens did not fail when the pulse shaper was used, and thus these tests were performed without a pulse shaper.

The incident, reflected, and transmitted pulses were used to calculate the forces at the incident bar-specimen (IB-S) and specimen-transmitter bar (S-TB) interfaces, F_1 and F_2 , respectively, following the procedure described in reference (12). The condition of stress equilibrium was checked using the nonequilibrium parameter, $R = 2(F_1 - F_2) / (F_1 + F_2)$ (15). Figure 8 shows the bar-specimen interface forces and the nonequilibrium parameter calculated for the 45 and 11.3° specimens (bar responses presented in figure 7). Stress equilibrium (R = 0.09) was achieved in the 45° specimen only at maximum/failure load. However, better stress equilibrium was achieved in the 11.3° specimen (R = 0.06 at failure). The average maximum force, F_{max} , was used to calculate the average axial strength of the specimen. Because the thickness of the adhesive bond is small as compared to the length of the incident bar, it is assumed that a volume element in the adhesive layer is under stress equilibrium (see figure 9). The axial strength was then transformed into normal and shear stresses along the failure plane (figure 9b).





Figure 7. Hopkinson bar responses of Hysol EA9359.3 induction-cured scarf-repaired composite specimens under axial compression.



 $Figure\ 8.\ Stress\ equilibrium\ in\ Hysol\ EA9359.3\ scarf-repaired\ composite\ specimens.$

Figure 10 shows a plot of axial strength of the specimen as a function of scarf angle for quasi-static and dynamic loading cases for the various adhesives. One important observation from these tests is that the dynamic axial strengths of the scarf joints were higher than the quasi-static axial strength by a factor of 2-3 for each scarf angle. The influence of scarf angle was similar to the results shown in figure 5 for the four-point beam tests. The dynamic axial strength increased as the scarf angle decreased, for all adhesives under dynamic and quasi-static loading conditions (with the 11.3° scarf-repaired Plexus MA425 specimen being the exception).




Figure 9. Stress analysis of scarf-repaired composite specimens under dynamic axial compressive load.




Figure 10. Axial compressive strength of scarf-repaired composite specimens under dynamic compressive load.

The loci of failure were found to be 50% in the adhesive/metal mesh interface and 50% between the adhesive and parent material in the case of Hysol adhesives (figure 11a), except for the 45° scarf for which the failure was 100% in the adhesive metal mesh interface. In the case of the Plexus adhesive joint, the loci of failure were found to be in the adhesive (figure 11b). These failure patterns were very similar to those obtained from quasi-static four-point bend tests.




Figure 11. Fracture surfaces of scarf-repaired composite specimens under dynamic axial compression.

The axial compressive strength for the Hysol 9359.3 adhesive together with the transformed stresses in the scarf plane are presented in figure 12a. Results showed that the adhesive bond was subjected to normal compressive stress that varied significantly with the scarf angle. However, the shear stress was relatively constant in the range of 40–60 MPa. This suggested that the failure was governed by the shear stress component. In figure 12b, shear stresses of various adhesives are compared in case of static and dynamic loads. The results showed that the dynamic shear stresses at failure were significantly higher than those obtained under static loading. Furthermore, the Hysol adhesives offered higher dynamic shear strength compared to the Plexus adhesive.




Figure 12. Stresses at failure in the rotated coordinate system of the scarf-repaired composite specimens.

7. Conclusions

The scarf patch repair scheme used in the present study is viable for level III repair of composite structural armor. The scheme uses practical scarf geometries for thick-section applications, requires only one-sided access for repair and vacuum consolidation, and provides rapid heating via induction to cure adhesives at elevated temperatures. The repair procedure was demonstrated using four adhesive systems. Simple test methods were proposed to apply realistic static and dynamic loads to composite backing plates with scarf repairs.

The repair efficiency of scarf repairs, having scarf angles much greater than commonly used in aerospace applications, was assessed in a four-point bending test. The baseline behavior exhibited compression failure on the specimen surface followed by progressive failure. Scarf-repaired beams failed catastrophically in the adhesive bond, while the virgin specimens exhibited a progressive compressive failure of the fibers on the specimen surface layer. This

difference in failure mode may indicate that the inherent energy-absorbing mechanisms of the composite were limited by the repair.

The results, however, have shown that complete renewal of stiffness is achievable for the elevated temperature cure adhesives (a slight reduction of 15% is measured for the low modulus adhesive). The degree of strength recovered (based on first damage in the baseline) from the repairs increased from ~10% to 20%, to 40%, and 60% for the 45, 18.4, and 11.3° scarf repairs, respectively.

In the dynamic experiments, scarf-repaired composite backing plates were subjected to compression loading using the SHPB. The dynamic axial strength for all adhesives was higher than the corresponding quasi-static data by a factor of 2-3 for each scarf angle. The dynamic axial strength increased as the scarf angle decreased, consistent with the four-point bend tests. The results showed that the dynamic shear strength in the scarf plane was also rate dependent and significantly greater than the static strengths. Higher rate impact testing is needed to fully characterize the strength and energy absorption capabilities of the scarf repair.

Based on the limited results generated for the adhesives considered in the present study, induction curing of Hysol EA9359.3 with a 11.3° scarf offered the best combination of structural and rate-dependent properties.

8. References

- 1. Gama, B. A.; Bogetti, T. A.; Fink, B. K.; Yu, C. J.; Claar, T. D.; Eifert, H. H.; Gillespie J. W., Jr. Aluminum Foam Integral Armor: A New Dimension in Armor Design. *Composite Structures* **2001**, *52*, 381–395.
- 2. Gama, B. A.; Gillespie, J. W., Jr.; Bogetti, T. A.; Fink, B. K. Innovative Design and Ballistic Performance of Lightweight Composite Integral Armor. *Technology for the U.S. Army's Transformation, SAE World Congress and Exposition*; paper no. 2001-01-0888; Detroit, MI, 5–8 March 2001.
- 3. Gama, B. A.; Gillespie, J. W., Jr. Mahfuz, H.; Bogetti, T. A.; Fink, B. K. Effect of Non-Linear Material Behavior on the Through-Thickness Stress Wave Propagation in Multi-Layer Hybrid Lightweight Armor. *International Conference on Computational Engineering and Sciences*, Los Angeles, CA, 21–25 August 2000; Atluri, S. N., Burst, F. W., Eds.; Tech Science Press: Palmdale, CA, Vol. I, pp 157–162.
- 4. Monib, A. M.; Gillespie, J. W., Jr. Damage Tolerance of Composite Laminates Subjected to Ballistic Impact. *Proceedings of ANTEC 98*, Society of Plastics Engineers, Brookfield, CT, 1998; pp 1463–1467.
- 5. Mahdi, S.; Gama, B. A.; Yarlagadda, S.; Gillespie, J. W., Jr. Effect of the Manufacturing Process on the Interfacial Properties and Structural Performance of Multi-Functional Composite Structures. *Composites Part A* **2003**, *34*, 635–647.
- 6. Huang, X. G.; Gillespie, J. W., Jr.; Kumar, V.; Gavin, L. Mechanics of Integral Armor: Discontinuous Ceramic-Cored Sandwich Structure Under Tension and Shear. *Composite Structures* **1996**, *36*, 81–90.
- 7. Davila, C. G.; Chen, T-K. Advanced Modeling Strategies for the Analysis of Tile-Reinforced Composite Armor. *Applied Composite Materials* **2000**, *7* (1), 51–68.
- 8. Gama, B. A.; Bogetti, T. A.; Fink, B. K.; Gillespie, J. W., Jr. Processing, Ballistic Testing and Repair of Composite Integral Armor, *Proceedings of the 32nd International SAMPE Technical Conference*, Boston, MA, 5–9 November 2000.
- 9. Gillespie, J. W., Jr.; Monib, A. M.; Carlsson, L. A. Damage Tolerance of Thick-Section S-2 Glass Fabric Composites Subjected to Ballistic Impact Loading. *Journal of Composite Materials* **January 2003**.

- 10. Gama, B. A.; Yarlagadda, S.; Bogetti, T. A.; Fink, B. K.; Gillespie, J. W., Jr. Repair of Composite Integral Armor. *Proceedings of the SAMPE 2001 Symposium and Exhibition, Materials and Processes*, Long Beach, CA, 6–10 May 2001.
- 11. Mahdi, S.; Gillespie, J. W., Jr. Finite Element Analysis of Tile-Reinforced Composite Structural Armor Subjected to Bending Loads. *Composites B: Engineering* May 2003.
- 12. ASM Handbook, Volume 8, Mechanical Testing and Evaluation; ASM International: Materials Park, OH, 2000.
- 13. Loctite Aerospace. Dexter Hysol Paste Adhesive and Specialty Resins Selector Guide. www.loctiteaero.com (accessed 2001).
- 14. Mahdi, S.; Kim, H.-J.; Gama, B. A.; Yarlagadda, S.; Gillespie, J. W., Jr. A Comparison of Oven-Cured and Induction-Cured Adhesively Bonded Composite Joints. *Journal of Composite Materials* **2003**, *37* (6), 519–542.
- 15. Ravichandran, G.; Subhash, G. Critical Appraisal of Limiting Strain Rates for Compression Testing of Ceramics in a Split-Hopkinson Pressure Bar. *J. Am. Ceram. Soc.* **1994**, 77, 263–267.

1 DEFENSE TECHNICAL
(PDF INFORMATION CTR
ONLY) DTIC OCA
8725 JOHN J KINGMAN RD
STE 0944
FT BELVOIR VA 22060-6218

- 1 COMMANDING GENERAL US ARMY MATERIEL CMD AMCRDA TF 5001 EISENHOWER AVE ALEXANDRIA VA 22333-0001
- I INST FOR ADVNCD TCHNLGY THE UNIV OF TEXAS AT AUSTIN 3925 W BRAKER LN STE 400 AUSTIN TX 78759-5316
- 1 US MILITARY ACADEMY
 MATH SCI CTR EXCELLENCE
 MADN MATH
 THAYER HALL
 WEST POINT NY 10996-1786
- 1 DIRECTOR
 US ARMY RESEARCH LAB
 IMNE AD IM DR
 2800 POWDER MILL RD
 ADELPHI MD 20783-1197
- 3 DIRECTOR
 US ARMY RESEARCH LAB
 AMSRD ARL CI OK TL
 2800 POWDER MILL RD
 ADELPHI MD 20783-1197
- 3 DIRECTOR
 US ARMY RESEARCH LAB
 AMSRD ARL CS IS T
 2800 POWDER MILL RD
 ADELPHI MD 20783-1197

NO. OF COPIES ORGANIZATION

ABERDEEN PROVING GROUND

1 DIR USARL AMSRD ARL CI OK TP (BLDG 4600)

- DIRECTOR
 US ARMY RESEARCH LAB
 AMSRD ARL SE L
 D SNIDER
 2800 POWDER MILL RD
 ADELPHI MD 20783-1197
- 1 DIRECTOR
 US ARMY RESEARCH LAB
 AMSRD ARL SE DE
 R ATKINSON
 2800 POWDER MILL RD
 ADELPHI MD 20783-1197
- 5 DIRECTOR
 US ARMY RESEARCH LAB
 AMSRD ARL WM MB
 A ABRAHAMIAN
 M BERMAN
 M CHOWDHURY
 T LI
 E SZYMANSKI
 2800 POWDER MILL RD
 ADELPHI MD 20783-1197
- 1 COMMANDER
 US ARMY MATERIEL CMD
 AMXMI INT
 5001 EISENHOWER AVE
 ALEXANDRIA VA 22333-0001
- 2 PM MAS SFAE AMO MAS MC PICATINNY ARSENAL NJ 07806-5000
- 3 COMMANDER
 US ARMY ARDEC
 AMSTA AR CC
 M PADGETT
 J HEDDERICH
 H OPAT
 PICATINNY ARSENAL NJ
 07806-5000
- 2 COMMANDER
 US ARMY ARDEC
 AMSTA AR AE WW
 E BAKER
 J PEARSON
 PICATINNY ARSENAL NJ
 07806-5000

- 1 COMMANDER US ARMY ARDEC AMSTA AR FSE PICATINNY ARSENAL NJ 07806-5000
- 1 COMMANDER US ARMY ARDEC AMSTA AR TD PICATINNY ARSENAL NJ 07806-5000
- 13 **COMMANDER US ARMY ARDEC** AMSTA AR CCH A **F ALTAMURA** M NICOLICH M PALATHINGUL D VO R HOWELL A VELLA M YOUNG L MANOLE S MUSALLI R CARR **M LUCIANO E LOGSDEN** T LOUZEIRO PICATINNY ARSENAL NJ 07806-5000
- 1 COMMANDER
 US ARMY ARDEC
 AMSTA AR CCH P
 J LUTZ
 PICATINNY ARSENAL NJ
 07806-5000
- 1 COMMANDER
 US ARMY ARDEC
 AMSTA AR FSF T
 C LIVECCHIA
 PICATINNY ARSENAL NJ
 07806-5000
- 1 COMMANDER US ARMY ARDEC AMSTA ASF PICATINNY ARSENAL NJ 07806-5000

- 1 COMMANDER
 US ARMY ARDEC
 AMSTA AR QAC T C
 J PAGE
 PICATINNY ARSENAL NJ
 07806-5000
- 1 COMMANDER
 US ARMY ARDEC
 AMSTA AR M
 D DEMELLA
 PICATINNY ARSENAL NJ
 07806-5000
- 3 COMMANDER
 US ARMY ARDEC
 AMSTA AR FSA
 A WARNASH
 B MACHAK
 M CHIEFA
 PICATINNY ARSENAL NJ
 07806-5000
- 2 COMMANDER
 US ARMY ARDEC
 AMSTA AR FSP G
 M SCHIKSNIS
 D CARLUCCI
 PICATINNY ARSENAL NJ
 07806-5000
- 2 COMMANDER
 US ARMY ARDEC
 AMSTA AR CCH C
 H CHANIN
 S CHICO
 PICATINNY ARSENAL NJ
 07806-5000
- 1 COMMANDER
 US ARMY ARDEC
 AMSTA AR QAC T
 D RIGOGLIOSO
 PICATINNY ARSENAL NJ
 07806-5000
- 1 COMMANDER
 US ARMY ARDEC
 AMSTA AR WET
 T SACHAR
 BLDG 172
 PICATINNY ARSENAL NJ
 07806-5000

- 1 US ARMY ARDEC INTELLIGENCE SPECIALIST AMSTA AR WEL F M GUERRIERE PICATINNY ARSENAL NJ 07806-5000
- 10 **COMMANDER** US ARMY ARDEC AMSTA AR CCH B P DONADIA F DONLON **P VALENTI C KNUTSON G EUSTICE** K HENRY J MCNABOC **G WAGNECZ** R SAYER **FCHANG** PICATINNY ARSENAL NJ 07806-5000
- 6 COMMANDER
 US ARMY ARDEC
 AMSTA AR CCL
 F PUZYCKI
 R MCHUGH
 D CONWAY
 E JAROSZEWSKI
 R SCHLENNER
 M CLUNE
 PICATINNY ARSENAL NJ
 07806-5000
- 1 PM ARMS SFAE GCSS ARMS BLDG 171 PICATINNY ARSENAL NJ 07806-5000
- 1 COMMANDER
 US ARMY ARDEC
 AMSTA AR WEA
 J BRESCIA
 PICATINNY ARSENAL NJ
 07806-5000
- 1 PM MAS SFAE AMO MAS PICATINNY ARSENAL NJ 07806-5000

- 1 PM MAS SFAE AMO MAS CHIEF ENGINEER PICATINNY ARSENAL NJ 07806-5000
- 1 PM MAS SFAE AMO MAS PS PICATINNY ARSENAL NJ 07806-5000
- 2 PM MAS SFAE AMO MAS LC PICATINNY ARSENAL NJ 07806-5000
- 1 COMMANDER
 US ARMY ARDEC
 PRODUCTION BASE
 MODERN ACTY
 AMSMC PBM K
 PICATINNY ARSENAL NJ
 07806-5000
- 1 COMMANDER
 US ARMY TACOM
 PM COMBAT SYSTEMS
 SFAE GCS CS
 6501 ELEVEN MILE RD
 WARREN MI 48397-5000
- 1 COMMANDER US ARMY TACOM AMSTA SF WARREN MI 48397-5000
- 1 DIRECTOR
 AIR FORCE RESEARCH LAB
 MLLMD
 D MIRACLE
 2230 TENTH ST
 WRIGHT PATTERSON AFB OH
 45433-7817
- 1 OFC OF NAVAL RESEARCH J CHRISTODOULOU ONR CODE 332 800 N QUINCY ST ARLINGTON VA 22217-5600
- 1 US ARMY CERL R LAMPO 2902 NEWMARK DR CHAMPAIGN IL 61822

- 1 COMMANDER
 US ARMY TACOM
 PM SURVIVABLE SYSTEMS
 SFAE GCSS W GSI H
 M RYZYI
 6501 ELEVEN MILE RD
 WARREN MI 48397-5000
- 1 COMMANDER
 US ARMY TACOM
 CHIEF ABRAMS TESTING
 SFAE GCSS W AB QT
 T KRASKIEWICZ
 6501 ELEVEN MILE RD
 WARREN MI 48397-5000
- 1 COMMANDER
 WATERVLIET ARSENAL
 SMCWV QAE Q
 B VANINA
 BLDG 44
 WATERVLIET NY 12189-4050
- 1 TNG, DOC, & CBT DEV ATZK TDD IRSA A POMEY FT KNOX KY 40121
- 2 HQ IOC TANK
 AMMUNITION TEAM
 AMSIO SMT
 R CRAWFORD
 W HARRIS
 ROCK ISLAND IL 61299-6000
- 2 COMMANDER
 US ARMY AMCOM
 AVIATION APPLIED TECH DIR
 J SCHUCK
 FT EUSTIS VA 23604-5577
- 1 NSWC DAHLGREN DIV CODE G06 DAHLGREN VA 22448
- 2 US ARMY CORPS OF ENGR
 CERD C
 T LIU
 CEW ET
 T TAN
 20 MASSACHUSETTS AVE NW
 WASHINGTON DC 20314

1 US ARMY COLD REGIONS RSCH & ENGRNG LAB P DUTTA 72 LYME RD HANOVER NH 03755

14 COMMANDER US ARMY TACOM AMSTA TR R R MCCLELLAND D THOMAS J BENNETT **D HANSEN AMSTA JSK** S GOODMAN J FLORENCE K IYER **D TEMPLETON** A SCHUMACHER AMSTA TR D D OSTBERG L HINOJOSA **B** RAJU AMSTA CS SF H HUTCHINSON

14 BENET LABS
AMSTA AR CCB
R FISCELLA
M SOJA
E KATHE
M SCAVULO
G SPENCER
P WHEELER
S KRUPSKI
J VASILAKIS
G FRIAR
R HASENBEIN
AMSTA CCB R
S SOPOK

E HYLAND D CRAYON

R DILLON

F SCHWARZ

WARREN MI 48397-5000

WATERVLIET NY 12189-4050

1 USA SBCCOM PM SOLDIER SPT AMSSB PM RSS A J CONNORS KANSAS ST NATICK MA 01760-5057

NO. OF COPIES ORGANIZATION

1 NSWC TECH LIBRARY CODE 323 17320 DAHLGREN RD DAHLGREN VA 22448

2 USA SBCCOM
MATERIAL SCIENCE TEAM
AMSSB RSS
J HERBERT
M SENNETT
KANSAS ST
NATICK MA 01760-5057

2 OFC OF NAVAL RESEARCH D SIEGEL CODE 351 J KELLY 800 N QUINCY ST ARLINGTON VA 22217-5660

1 NSWC CRANE DIVISION M JOHNSON CODE 20H4 LOUISVILLE KY 40214-5245

2 NSWC U SORATHIA C WILLIAMS CD 6551 9500 MACARTHUR BLVD WEST BETHESDA MD 20817

2 COMMANDER
NSWC
CARDEROCK DIVISION
R PETERSON CODE 2020
M CRITCHFIELD CODE 1730
BETHESDA MD 20084

8 DIRECTOR
US ARMY NGIC
D LEITER MS 404
M HOLTUS MS 301
M WOLFE MS 307
S MINGLEDORF MS 504
J GASTON MS 301
W GSTATTENBAUER MS 304
R WARNER MS 305
J CRIDER MS 306
2055 BOULDERS RD
CHARLOTTESVILLE VA
22911-8318

1 NAVAL SEA SYSTEMS CMD D LIESE 1333 ISAAC HULL AVE SE 1100 WASHINGTON DC 20376-1100

1 EXPEDITIONARY WARFARE DIV N85 F SHOUP 2000 NAVY PENTAGON WASHINGTON DC 20350-2000

US ARMY SBCCOM

- SOLDIER SYSTEMS CENTER
 BALLISTICS TEAM
 J WARD
 W ZUKAS
 P CUNNIFF
 J SONG
 MARINE CORPS TEAM
 J MACKIEWICZ
 BUS AREA ADVOCACY TEAM
 W HASKELL
 AMSSB RCP SS
 W NYKVIST
 S BEAUDOIN
 KANSAS ST
 NATICK MA 01760-5019
- 7 US ARMY RESEARCH OFC
 A CROWSON
 H EVERETT
 J PRATER
 G ANDERSON
 D STEPP
 D KISEROW
 J CHANG
 PO BOX 12211
 RESEARCH TRIANGLE PARK NC
 27709-2211
- 1 AFRL MLBC 2941 P ST RM 136 WRIGHT PATTERSON AFB OH 45433-7750
- 1 DIRECTOR LOS ALAMOS NATL LAB F L ADDESSIO T 3 MS 5000 PO BOX 1633 LOS ALAMOS NM 87545

- 8 NSWC
 J FRANCIS CODE G30
 D WILSON CODE G32
 R D COOPER CODE G32
 J FRAYSSE CODE G33
 E ROWE CODE G33
 T DURAN CODE G33
 L DE SIMONE CODE G33
 R HUBBARD CODE G33
 DAHLGREN VA 22448
- 1 NSWC
 CARDEROCK DIVISION
 R CRANE CODE 6553
 9500 MACARTHUR BLVD
 WEST BETHESDA MD 20817-5700
- 1 AFRL MLSS R THOMSON 2179 12TH ST RM 122 WRIGHT PATTERSON AFB OH 45433-7718
- 2 AFRL F ABRAMS J BROWN BLDG 653 2977 P ST STE 6 WRIGHT PATTERSON AFB OH 45433-7739
- 5 DIRECTOR LLNL R CHRISTENSEN S DETERESA F MAGNESS M FINGER MS 313 M MURPHY L 282 PO BOX 808 LIVERMORE CA 94550
- 1 AFRL MLS OL L COULTER 5851 F AVE BLDG 849 RM AD1A HILL AFB UT 84056-5713
- OSD
 JOINT CCD TEST FORCE
 OSD JCCD
 R WILLIAMS
 3909 HALLS FERRY RD
 VICKSBURG MS 29180-6199

- 3 DARPA M VANFOSSEN S WAX L CHRISTODOULOU 3701 N FAIRFAX DR ARLINGTON VA 22203-1714
- 2 SERDP PROGRAM OFC
 PM P2
 C PELLERIN
 B SMITH
 901 N STUART ST STE 303
 ARLINGTON VA 22203
- 1 OAK RIDGE NATL LAB R M DAVIS PO BOX 2008 OAK RIDGE TN 37831-6195
- OAK RIDGE NATL LAB C EBERLE MS 8048 PO BOX 2008 OAK RIDGE TN 37831
- 3 DIRECTOR
 SANDIA NATL LABS
 APPLIED MECHS DEPT
 MS 9042
 J HANDROCK
 Y R KAN
 J LAUFFER
 PO BOX 969
 LIVERMORE CA 94551-0969
- OAK RIDGE NATL LAB C D WARREN MS 8039 PO BOX 2008 OAK RIDGE TN 37831
- 4 NIST
 M VANLANDINGHAM MS 8621
 J CHIN MS 8621
 J MARTIN MS 8621
 D DUTHINH MS 8611
 100 BUREAU DR
 GAITHERSBURG MD 20899
- 1 HYDROGEOLOGIC INC SERDP ESTCP SPT OFC S WALSH 1155 HERNDON PKWY STE 900 HERNDON VA 20170

- 3 NASA LANGLEY RESEARCH CTR AMSRD ARL VS W ELBER MS 266 F BARTLETT JR MS 266 G FARLEY MS 266 HAMPTON VA 23681-0001
- 1 NASA LANGLEY RESEARCH CTR T GATES MS 188E HAMPTON VA 23661-3400
- 1 FHWA
 E MUNLEY
 6300 GEORGETOWN PIKE
 MCLEAN VA 22101
- 1 USDOT FEDERAL RAILROAD M FATEH RDV 31 WASHINGTON DC 20590
- 3 CYTEC FIBERITE
 R DUNNE
 D KOHLI
 R MAYHEW
 1300 REVOLUTION ST
 HAVRE DE GRACE MD 21078
- 1 DIRECTOR
 NGIC
 IANG TMT
 2055 BOULDERS RD
 CHARLOTTESVILLE VA
 22911-8318
- 1 SIOUX MFG
 B KRIEL
 PO BOX 400
 FT TOTTEN ND 58335
- 2 3TEX CORP
 A BOGDANOVICH
 J SINGLETARY
 109 MACKENAN DR
 CARY NC 27511
- 1 3M CORP J SKILDUM 3M CENTER BLDG 60 IN 01 ST PAUL MN 55144-1000

NO. OF COPIES	<u>ORGANIZATION</u>	NO. OF COPIES	<u>ORGANIZATION</u>
1	DIRECTOR DEFENSE INTLLGNC AGNCY TA 5 K CRELLING WASHINGTON DC 20310	1	ROM DEVELOPMENT CORP R O MEARA 136 SWINEBURNE ROW BRICK MARKET PLACE NEWPORT RI 02840
1	ADVANCED GLASS FIBER YARNS T COLLINS 281 SPRING RUN LANE STE A DOWNINGTON PA 19335	2	TEXTRON SYSTEMS T FOLTZ M TREASURE 1449 MIDDLESEX ST LOWELL MA 01851
1	COMPOSITE MATERIALS INC D SHORTT 19105 63 AVE NE PO BOX 25 ARLINGTON WA 98223	1	O GARA HESS & EISENHARDT M GILLESPIE 9113 LESAINT DR FAIRFIELD OH 45014
1	JPS GLASS L CARTER PO BOX 260 SLATER RD SLATER SC 29683	2	MILLIKEN RESEARCH CORP H KUHN M MACLEOD PO BOX 1926 SPARTANBURG SC 29303
1	COMPOSITE MATERIALS INC R HOLLAND 11 JEWEL CT ORINDA CA 94563	1	CONNEAUGHT INDUSTRIES INC J SANTOS PO BOX 1425 COVENTRY RI 02816
1	COMPOSITE MATERIALS INC C RILEY 14530 S ANSON AVE SANTA FE SPRINGS CA 90670	1	ARMTEC DEFENSE PRODUCTS S DYER 85 901 AVE 53 PO BOX 848 COACHELLA CA 92236
2	SIMULA J COLTMAN R HUYETT 10016 S 51ST ST PHOENIX AZ 85044	1	NATL COMPOSITE CTR T CORDELL 2000 COMPOSITE DR KETTERING OH 45420
2	PROTECTION MATERIALS INC M MILLER F CRILLEY 14000 NW 58 CT MIAMI LAKES FL 33014	3	PACIFIC NORTHWEST LAB M SMITH G VAN ARSDALE R SHIPPELL PO BOX 999 RICHLAND WA 99352
2	FOSTER MILLER M ROYLANCE W ZUKAS 195 BEAR HILL RD WALTHAM MA 02354-1196	1	SAIC M PALMER 1410 SPRING HILL RD STE 400 MS SH4 5 MCLEAN VA 22102

- 1 ALLIANT TECHSYSTEMS INC 4700 NATHAN LN N PLYMOUTH MN 55442-2512
- 1 APPLIED COMPOSITES W GRISCH 333 NORTH SIXTH ST ST CHARLES IL 60174
- 1 CUSTOM ANALYTICAL ENG SYS INC A ALEXANDER 13000 TENSOR LANE NE FLINTSTONE MD 21530
- 1 AAI CORP
 DR N B MCNELLIS
 PO BOX 126
 HUNT VALLEY MD 21030-0126
- 1 OFC DEPUTY UNDER SEC DEFNS J THOMPSON 1745 JEFFERSON DAVIS HWY CRYSTAL SQ 4 STE 501 ARLINGTON VA 22202
- 3 ALLIANT TECHSYSTEMS INC J CONDON E LYNAM J GERHARD WV01 16 STATE RT 956 PO BOX 210 ROCKET CENTER WV 26726-0210
- PROJECTILE TECHNOLOGY INC 515 GILES ST HAVRE DE GRACE MD 21078
- 1 HEXCEL INC
 R BOE
 PO BOX 18748
 SALT LAKE CITY UT 84118
- 1 PRATT & WHITNEY C WATSON 400 MAIN ST MS 114 37 EAST HARTFORD CT 06108

- 5 NORTHROP GRUMMAN
 B IRWIN
 K EVANS
 D EWART
 A SHREKENHAMER
 J MCGLYNN
 BLDG 160 DEPT 3700
 1100 WEST HOLLYVALE ST
 AZUSA CA 91701
- HERCULES INC
 HERCULES PLAZA
 WILMINGTON DE 19894
- 1 BRIGS COMPANY J BACKOFEN 2668 PETERBOROUGH ST HERNDON VA 22071-2443
- I ZERNOW TECHNICAL SERVICES L ZERNOW 425 W BONITA AVE STE 208 SAN DIMAS CA 91773
- 1 GENERAL DYNAMICS OTS L WHITMORE 10101 NINTH ST NORTH ST PETERSBURG FL 33702
- 2 GENERAL DYNAMICS OTS FLINCHBAUGH DIV K LINDE T LYNCH PO BOX 127 RED LION PA 17356
- 1 GKN WESTLAND AEROSPACE D OLDS 450 MURDOCK AVE MERIDEN CT 06450-8324
- 2 BOEING ROTORCRAFT
 P MINGURT
 P HANDEL
 800 B PUTNAM BLVD
 WALLINGFORD PA 19086

- 5 SIKORSKY AIRCRAFT G JACARUSO T CARSTENSAN B KAY S GARBO MS S330A J ADELMANN 6900 MAIN ST PO BOX 9729 STRATFORD CT 06497-9729
- 1 AEROSPACE CORP G HAWKINS M4 945 2350 E EL SEGUNDO BLVD EL SEGUNDO CA 90245
- 2 CYTEC FIBERITE M LIN W WEB 1440 N KRAEMER BLVD ANAHEIM CA 92806
- 2 UDLP G THOMAS M MACLEAN PO BOX 58123 SANTA CLARA CA 95052
- 1 UDLP WARREN OFC A LEE 31201 CHICAGO RD SOUTH SUITE B102 WARREN MI 48093
- 2 UDLP R BRYNSVOLD P JANKE MS 170 4800 EAST RIVER RD MINNEAPOLIS MN 55421-1498
- 1 LOCKHEED MARTIN SKUNK WORKS D FORTNEY 1011 LOCKHEED WAY PALMDALE CA 93599-2502
- 1 LOCKHEED MARTIN R FIELDS 5537 PGA BLVD SUITE 4516 ORLANDO FL 32839

- NORTHRUP GRUMMAN CORP ELECTRONIC SENSORS & SYSTEMS DIV E SCHOCH MS V 16 1745A W NURSERY RD LINTHICUM MD 21090
- 1 GDLS DIVISION D BARTLE PO BOX 1901 WARREN MI 48090
- 2 GDLS D REES M PASIK PO BOX 2074 WARREN MI 48090-2074
- 1 GDLS MUSKEGON OPER M SOIMAR 76 GETTY ST MUSKEGON MI 49442
- I GENERAL DYNAMICS
 AMPHIBIOUS SYS
 SURVIVABILITY LEAD
 G WALKER
 991 ANNAPOLIS WAY
 WOODBRIDGE VA 22191
- INST FOR ADVANCED
 TECH
 H FAIR
 I MCNAB
 P SULLIVAN
 S BLESS
 W REINECKE
 C PERSAD
 3925 W BRAKER LN STE 400
 AUSTIN TX 78759-5316
- 1 ARROW TECH ASSOC 1233 SHELBURNE RD STE D8 SOUTH BURLINGTON VT 05403-7700
- 1 R EICHELBERGER CONSULTANT 409 W CATHERINE ST BEL AIR MD 21014-3613

- 1 SAIC
 G CHRYSSOMALLIS
 8500 NORMANDALE LAKE BLVD
 SUITE 1610
 BLOOMINGTON MN 55437-3828
- 1 UCLA MANE DEPT ENGR IV H T HAHN LOS ANGELES CA 90024-1597
- 2 UNIV OF DAYTON
 RESEARCH INST
 R Y KIM
 A K ROY
 300 COLLEGE PARK AVE
 DAYTON OH 45469-0168
- 1 UMASS LOWELL
 PLASTICS DEPT
 N SCHOTT
 1 UNIVERSITY AVE
 LOWELL MA 01854
- 1 IIT RESEARCH CTR D ROSE 201 MILL ST ROME NY 13440-6916
- 1 GA TECH RESEARCH INST GA INST OF TCHNLGY P FRIEDERICH ATLANTA GA 30392
- 1 MICHIGAN ST UNIV MSM DEPT R AVERILL 3515 EB EAST LANSING MI 48824-1226
- 1 UNIV OF WYOMING D ADAMS PO BOX 3295 LARAMIE WY 82071
- 1 PENN STATE UNIV R S ENGEL 245 HAMMOND BLDG UNIVERSITY PARK PA 16801

- 2 PENN STATE UNIV
 R MCNITT
 C BAKIS
 212 EARTH ENGR
 SCIENCES BLDG
 UNIVERSITY PARK PA 16802
- 1 PURDUE UNIV SCHOOL OF AERO & ASTRO C T SUN W LAFAYETTE IN 47907-1282
- 1 STANFORD UNIV
 DEPT OF AERONAUTICS
 & AEROBALLISTICS
 S TSAI
 DURANT BLDG
 STANFORD CA 94305
- 1 UNIV OF MAINE ADV STR & COMP LAB R LOPEZ ANIDO 5793 AEWC BLDG ORONO ME 04469-5793
- 1 JOHNS HOPKINS UNIV APPLIED PHYSICS LAB P WIENHOLD 11100 JOHNS HOPKINS RD LAUREL MD 20723-6099
- 1 UNIV OF DAYTON
 J M WHITNEY
 COLLEGE PARK AVE
 DAYTON OH 45469-0240
- 1 NORTH CAROLINA ST UNIV CIVIL ENGINEERING DEPT W RASDORF PO BOX 7908 RALEIGH NC 27696-7908
- 5 UNIV OF DELAWARE
 CTR FOR COMPOSITE MTRLS
 J GILLESPIE
 M SANTARE
 S YARLAGADDA
 S ADVANI
 D HEIDER
 201 SPENCER LAB
 NEWARK DE 19716

NO. OF NO. OF COPIES ORGANIZATION **COPIES ORGANIZATION DEPT OF MTRLS** ABERDEEN PROVING GROUND **SCIENCE & ENGRG** UNIV OF ILLINOIS 1 US ARMY ATC AT URBANA CHAMPAIGN CSTE DTC AT AC I J ECONOMY W C FRAZER 1304 WEST GREEN ST 115B 400 COLLERAN RD URBANA IL 61801 APG MD 21005-5059 UNIV OF MARYLAND 91 **DIR USARL** DEPT OF AEROSPACE ENGRG AMSRD ARL CI A J VIZZINI AMSRD ARL O AP EG COLLEGE PARK MD 20742 M ADAMSON AMSRD ARL SL BA DREXEL UNIV AMSRD ARL SL BB A S D WANG D BELY 3141 CHESTNUT ST AMSRD ARL WM PHILADELPHIA PA 19104 J SMITH **H WALLACE** UNIV OF TEXAS AT AUSTIN AMSRD ARL WM B CTR FOR ELECTROMECHANICS A HORST J PRICE T KOGLER A WALLS AMSRD ARL WM BA J KITZMILLER **DLYON** 10100 BURNET RD AMSRD ARL WM BC AUSTIN TX 78758-4497 J NEWILL **P PLOSTINS** VA POLYTECHNICAL A ZIELINSKI **INST & STATE UNIV** AMSRD ARL WM BD DEPT OF ESM **P CONROY** M W HYER **B FORCH** K REIFSNIDER M LEADORE R JONES **C LEVERITT** BLACKSBURG VA 24061-0219 R LIEB R PESCE RODRIGUEZ SOUTHWEST RESEARCH INST **B RICE ENGR & MATL SCIENCES DIV** AMSRD ARL WM BF J RIEGEL S WILKERSON 6220 CULEBRA RD AMSRD ARL WM M PO DRAWER 28510 **B FINK** SAN ANTONIO TX 78228-0510 J MCCAULEY AMSRD ARL WM MA **BATELLE NATICK OPERS** L GHIORSE **B HALPIN** S MCKNIGHT 313 SPEEN ST E WETZEL NATICK MA 01760 AMSRD ARL WM MB J BENDER DIRECTOR T BOGETTI US ARMY RESEARCH LAB L BURTON AMSRD ARL WM MB R CARTER A FRYDMAN K CHO 2800 POWDER MILL RD W DE ROSSET

G DEWING R DOWDING W DRYSDALE

ADELPHI MD 20783-1197

NO. OF <u>COPIES</u> <u>ORGANIZATION</u>

R EMERSON D HENRY D HOPKINS R KASTE L KECSKES M MINNICINO B POWERS D SNOHA J SOUTH M STAKER J SWAB J TZENG

P BAKER
AMSRD ARL WM TC
R COATES
AMSRD ARL WM TD
D DANDEKAR
T HADUCH
T MOYNIHAN
M RAFTENBERG
S SCHOENFELD
T WEERASOORIYA
AMSRD ARL WM TE
A NIILER

J POWELL

AMSRD ARL WM TB

AMSRD ARL WM MC

J BEATTY R BOSSOLI E CHIN

S CORNELISON

D GRANVILLE B HART J LASALVIA

J MONTGOMERY

F PIERCE E RIGAS

W SPURGEON

AMSRD ARL WM MD

B CHEESEMAN

P DEHMER

R DOOLEY

G GAZONAS

S GHIORSE

C HOPPEL

M KLUSEWITZ

WROY

J SANDS

D SPAGNUOLO

S WALSH

S WOLF

AMSRD ARL WM RP

J BORNSTEIN

C SHOEMAKER

AMSRD ARL WM T

B BURNS

AMSRD ARL WM TA

W BRUCHEY

M BURKINS

W GILLICH

B GOOCH

T HAVEL

E HORWATH

M NORMANDIA

J RUNYEON

M ZOLTOSKI

1 LTD
R MARTIN
MERL
TAMWORTH RD
HERTFORD SG13 7DG

1 SMC SCOTLAND
P W LAY
DERA ROSYTH
ROSYTH ROYAL DOCKYARD
DUNFERMLINE FIFE KY 11 2XR
UK

1 CIVIL AVIATION
ADMINSTRATION
T GOTTESMAN
PO BOX 8
BEN GURION INTRNL AIRPORT
LOD 70150
ISRAEL

1 AEROSPATIALE
S ANDRE
A BTE CC RTE MD132
316 ROUTE DE BAYONNE
TOULOUSE 31060
FRANCE

1 DRA FORT HALSTEAD P N JONES SEVEN OAKS KENT TN 147BP UK

1 SWISS FEDERAL ARMAMENTS WKS W LANZ ALLMENDSTRASSE 86 3602 THUN SWITZERLAND

1 DYNAMEC RESEARCH LAB AKE PERSSON BOX 201 SE 151 23 SODERTALJE SWEDEN

NO. OF COPIES ORGANIZATION

1 ISRAEL INST OF TECHLGY S BODNER FACULTY OF MECHANICAL ENGR HAIFA 3200 ISRAEL

1 DSTO
WEAPONS SYSTEMS DIVISION
N BURMAN RLLWS
SALISBURY
SOUTH AUSTRALIA 5108
AUSTRALIA

1 DEF RES ESTABLISHMENT
VALCARTIER
A DUPUIS
2459 BLVD PIE XI NORTH
VALCARTIER QUEBEC
CANADA
PO BOX 8800 COURCELETTE
GOA IRO QUEBEC
CANADA

1 ECOLE POLYTECH
J MANSON
DMX LTC
CH 1015 LAUSANNE
SWITZERLAND

1 TNO DEFENSE RESEARCH R IJSSELSTEIN ACCOUNT DIRECTOR R&D ARMEE PO BOX 6006 2600 JA DELFT THE NETHERLANDS

2 FOA NATL DEFENSE RESEARCH
ESTAB
DIR DEPT OF WEAPONS &
PROTECTION
B JANZON
R HOLMLIN
S 172 90 STOCKHOLM
SWEDEN

NO. OF

COPIES ORGANIZATION

- 2 DEFENSE TECH & PROC AGENCY GROUND I CREWTHER GENERAL HERZOG HAUS 3602 THUN SWITZERLAND
- 1 MINISTRY OF DEFENCE RAFAEL ARMAMENT DEVELOPMENT AUTH M MAYSELESS PO BOX 2250 HAIFA 31021 ISRAEL
- I TNO DEFENSE RESEARCH
 I H PASMAN
 POSTBUS 6006
 2600 JA DELFT
 THE NETHERLANDS
- B HIRSCH
 TACHKEMONY ST 6
 NETAMUA 42611
 ISRAEL
- 1 DEUTSCHE AEROSPACE AG DYNAMICS SYSTEMS M HELD PO BOX 1340 D 86523 SCHROBENHAUSEN GERMANY